

SERVICE BULLETIN

0019

Service bulletins are issued by *Maine Energy Systems* at irregular intervals to alert Installers of common issues of installations and are also used to pass information of interest or information concerning parts replacement that may be considered unusual or unscheduled for boilers already in service.

Subject: All FleXilo Storage System motor connectors

Models: All FleXilo Storage Systems

Problem: Wiring no longer colored, making correct connections difficult.

Many of the motors for KGT and possibly for Metering Devices for FleXilo storage systems will have all black wires, where they previously had 5 different colors. It was the colors which were the best and most dependable means of correctly connecting these motors.

As a new manner of correctly making these wiring connections to the boiler or furnace, there is a new label inside the black disconnect / plug that comes supplied with the motors. This label, clearly displays the terminal strip number of the boiler or furnace for each individual wire.

If you get a motor without the label clearly displaying terminal strip numbers, call Maine Energy Systems for clarification and direction. DO NOT PROCEED OTHERWISE.

Connecting these wires incorrectly can do permanent damage to the boiler / furnace controller.

CAUTION!!! If already connected to the boiler / furnace, this plug is ALWAYS ENERGIZED, not just when the motor is running!

NOTE: